

03500.017693



C of C
PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:

Akiyoshi YOKOI

Appl. No.: 10/697,323

Filed: October 31, 2003

For: REMANUFACTURING METHOD
FOR PROCESS CARTRIDGE

) Examiner: Sandra L. Brase
:
:) Group Art Unit: 2852
:
:) U.S. Patent No.: US 6,941,092 B2
:
:) Issued: September 6, 2005
:
:) May 11, 2006

Certificate

MAY 15 2006

of Correction

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION UNDER RULE 322

Sir:


It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes. A Certificate of Correction form (Form PTO-1050), in duplicate, is enclosed.

Although no fees are believed to be necessary, any fees deemed necessitated by this paper may be charged to Deposit Account No. 06-1205. A duplicate copy of this paper is enclosed.

MAY 15 2006

Patentee's undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,



Gary M. Jacobs
Attorney for Patentee
Registration No. 28,861

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200
GMJ/lw

DC_MAIN 221926v1

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only!

PRINTER'S TRIM LINE

PATENT NO. : US 6,941,092 B2
DATED : September 6, 2005
INVENTOR(S) : Akiyoshi YOKOI

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 14

Line 4, "developer" should read --developer; (New Paragraph) a first coupling frame (side cover 22) for coupling one end side of the photosensitive member unit 21 and one end side of the developing unit 20 to each other; and--.

Line 5, "or" should read --for--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,941,092 B2

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

(Form#30) GMJ/lw 221927v1

MAY 15 2005

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,941,092 B2

DATED : September 6, 2005

INVENTOR(S) : Akiyoshi YOKOI

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 14

Line 4, "developer" should read --developer; (New Paragraph) a first coupling frame (side cover 22) for coupling one end side of the photosensitive member unit 21 and one end side of the developing unit 20 to each other; and--.

Line 5, "or" should read --for--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,941,092 B2

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

(Form#30) GMJ/lw 221927v1



MAY 15 2006